



DEPARTMENT OF  
WATER RESOURCES

# BEAR RIVER AREA *Fact Sheet* **Site 10.1**

Critical Levee Erosion Site

## Emergency Levee Repairs

### Location

River: Bear River

River Mile: 10.1

Latitude/Longitude:

38.995261/-121.428594

Nearest Impact Area:

Wheatland

County: Yuba

Bank: Right

### Type of Damage

Bank erosion

### Length of Repair

850 feet (approximate)

### Repair Type

Rock slope protection

### Lead Agency

Department of Water Resources

For further information,  
please contact:

**Elizabeth Scott**  
DWR Public Affairs Office  
(916) 835-5344  
[leveerepair@water.ca.gov](mailto:leveerepair@water.ca.gov)

DEPARTMENT OF WATER RESOURCES  
PO Box 942836, Sacramento, CA 94236

[www.levees.water.ca.gov](http://www.levees.water.ca.gov)

